Pedestrian Safety at CSUSB PDC – Items of Concern

February 2018

ITEM	SAFETY OBSERVATION	EH&S RECOMMENDED ACTION	RESPONSIBLE DEPARTMENT(S)
1	There is a short concrete ramp which leads from the east side of Indian Wells Theater to parking Lot A. This ramp is not ADA accessible because of the steep slope and lack of handrails. On the IWT end of the ramp, there is a sign that reads "(Wheelchair) Accessible Path →". This sign sits to the left of the ramp and points right, which is confusing to those who might misinterpret the path going straight ahead as being ADA compliant.	Install a "(Wheelchair) Not Accessible ↑" sign at the IWT entrance to the ramp, adjacent to the existing sign. The Not Accessible sign is present at the Lot A entrance. Install an "Accessible Path ←" sign at the Lot A entrance. (See pictures 1 and 2)	Facilities Planning, Design and Construction
2	Regarding the wheelchair-accessible ramp adjacent to Indian Wells Theater: there is a gap in the handrail where the ramp makes a 90- degree turn. The gap is big enough that someone in a wheelchair could veer off the ramp and fall.	Install a handrail to close the gap.	Facilities Planning, Design and Construction
3	Vehicles turning right onto Berger Road from Berger Drive West (access road to Cook St) are not coming to a complete stop at the intersection. Based on EH&S' short observation, approximately 50 percent of motorists are "rolling" through the intersection.	Enact enforcement measures at the intersection.	Parking Services / University Police
4	The intersection of Berger Road and Berger Drive West is poorly lit at night.	Install sufficient street lighting at the intersection.	Facilities Planning, Design and Construction
5	Many motorists drive too fast on Berger Road and do not yield the right-of-way to pedestrians. Pedestrians who cross to and from Lot B are at higher risk of being hit.	Install crosswalks with ground-embedded lights which can be activated by the pedestrian. Install speed bumps to slow traffic through Berger Road.	Facilities Planning, Design and Construction / Parking Services

Page | 1 of 2 CSUSB EHS – (909) 537-5179

Berger Drive West and the north end of Berger Road have a speed limit of 15 mph. The south end of Berger Road and Berger Drive South (access road to Frank Sinatra Dr) have a speed limit of 25 mph. Motorists entering Berger Road from the south may be oblivious to the speed limit reduction as they approach the CSUSB campus.

If possible, set the speed limit at 15 mph for all of Berger Road and Berger Drive South.

Consider installing real-time "Your Speed" electronic sign on Berger Road facing northbound traffic. Enact enforcement measures to deter motorists using Berger Road as a shortcut to Cook St from speeding.

Parking Services / University Police

PICTURES



Picture 1: Ramp at Indian Wells Theater entrance



Picture 2: Ramp at Lot A entrance

Page | 2 of 2 CSUSB EHS – (909) 537-5179