



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT




FACILITY NAME CAL STATE UNIVERSITY			REINSPECTION DATE Next Routine	INSPECTOR Jeanette Guido	DATE 6/15/2018
LOCATION 5500 UNIVERSITY PKWY, SAN BERNARDINO, CA 92407			PERMIT EXPIRATION	IDENTIFIER: Dorm Pool	
TIME IN 10:00 AM	TIME OUT 10:35 AM	FACILITY ID FA0006500	RELATED ID PR0014827	PE 3603	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION
					RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 01 - NO FURTHER ACTION REQUIRED

RECREATIONAL HEALTH - Public School Pool / Spa

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	45
required flow (gpm)	414
volume (gal)	240,000
area (sq ft)	No Data
occupancy	143

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: The purpose of the follow-up was to verify that the pump was continuously running during hours of operation.

Observed pump to be operating.

Ensure pump is operating whenever pool is available for use and as needed.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Benjamin Virzi
TITLE: EHS Specialist

Total # of Images: 0